

**OVERHAUL SPECIFICATION**

INNER COIL, BAFFLES, AND READING SEALS -  
MODEL C-450 AND C-45H


Overhaul Specification 9811

ISSUED April 29, 1953

REVISED April 14, 1954

  
F. B. Taylor  
Writer

  
R. B. Boworth  
Chief Liaison Engineer

  
M. D. Lapp  
Project Engineer

E-371

  
A. S. Olsowicz  
Chief Project Engineer, Military

  
W. C. Grier  
USAF Quality Control

## OVERHAUL SPECIFICATION 9811

PAGE 1 OF 9

TITLE INNER COOL, BAFFLES, AND ENGINE SEALS - MODEL C-45G AND C-45HISSUED 4-29-53DRAWN BY T. R. TaylorREVISED 4-14-54

## I. SCOPE

1.1 Purpose. - The purpose of this specification is to authorize the use of reconditioned parts and provide reconditioning instructions for component parts of the 64-186910 engine inner cowling assembly, the 189110 engine baffles installation, and the engine seals (segment assemblies) as installed in aircraft received for overhaul, and instructions for modifications required to adapt them for installation in C-45G and C-45H aircraft in accordance with Drawing 694-186910 engine inner cowl assembly, Drawing 189110 engine baffles installation and Drawing 694-189001 engine seals installation.

1.2 Application. - All reconditioning operations and repairs covered by this specification may be accomplished where required without further authorization. Repairs not authorized by this specification cannot be performed without further authorization.

1.3 List of Pages and Revisions. - This specification consists of the pages listed below. An asterisk (\*) denotes the page revised by the current revision.

| <u>Page</u> | <u>Date</u> | <u>Description of Revision</u>   | <u>Serial Effectivity</u> |
|-------------|-------------|--|---------------------------|
| * 1         | 4-14-54     | Note Revision  | Record change             |
| 2           | 4-29-53     |  |                           |
| 3           | 4-29-53     |  |                           |
| 4           | 1-20-54     | Revise Para. 3.2(a) to scrap inner cowls made from non-corrosion-resistant steel                           | AF-704                    |
| 5           | 2-18-54     | Change Para. 3.3.1 to permit flexibility in reconditioning procedures                                      | Record change             |
| 6           | 4-29-53     |  |                           |
| * 7         | 4-14-54     | Add Step (g) Para. 3.4.1   | Record change             |
| 8           | 2-18-54     | Add Para. 4.2.1(f) to authorize use of reconditioned inner cowls with discoloration due to heat and carbon | Record change             |
| 9           | 4-29-53     |  |                           |

**2. APPLICABLE PUBLICATIONS**

**2.1 Specifications:**

**2.1.1 Beech -**

FS 3701 Finish Specification for Model C-45G and C-45H Aircraft  
 OS 7002 Cleaning Procedures for Reconditioned Aircraft  
 OS 7003 General Acceptable Quality Standards

**3. REQUIREMENTS**

**3.1 Parts Involved:**

**3.1.1 Parts Not Used.** - The parts listed below will not be reused and will be disposed of at the direction of the customer.

**3.1.1.1 Engine Inner Cowling Assembly 84-185910.-**

|              |                 |
|--------------|-----------------|
| 84-185896    | Seal            |
| 84-185022    | Angle           |
| 84-185910-18 | Kearsarge strip |
| 84-185910-19 | Kearsarge strip |
| No. 100      | Dzus spring     |

**3.1.1.2 Segment Assemblies 84-184880, 84-185881, 84-185882, 84-185883, 84-185884, 84-185885, and 84-185886.-**

|           |      |
|-----------|------|
| 84-185887 | Seal |
| 84-185888 | Seal |
| 84-185889 | Seal |
| 84-185890 | Seal |
| 84-185891 | Seal |

|                  |                       |   |         |                            |                            |      |
|------------------|-----------------------|---|---------|----------------------------|----------------------------|------|
| WRITTEN BY       | <i>W. Fitzpatrick</i> | DATE ISSUED                             | 1-29-53 | OVERHAUL SPECIFICATION     |                            |      |
| PROJECT ENGINEER | <i>C. H. C.</i>       | INNER COWL, BAFFLES, AND ENGINE SEALS - |         |                            |                            |      |
| APPROVAL         | <i>[Signature]</i>    | DATE REVISED                            |         | Beech Aircraft CORPORATION | OVERHAUL SPECIFICATION NO. | PAGE |
| APPROVAL         | <i>[Signature]</i>    |   |         | Wichita, Kansas            | 9811                       | 2    |
| E-358A           |                       |   |         |                            |                            |      |

3.1.1.2 Segment Assemblies 84-185880, 84-185881, 84-185882, 84-185883, 84-185884, 84-185885, and 84-185886.- (Continued)

84-185892 Seal  
84-189893 Seal  
84-189894 Seal  
84-189895 Seal

3.1.2. Parts to be Reconditioned. - The following parts are to be reconditioned in accordance with the instructions contained herein. "Reconditioned" means the disassembly, cleaning, inspection and correction of discrepancies, repair and/or replacement of components, and modifications to assure an operationally safe and serviceable aircraft.

3.1.2.1. Engine Inner Cowling Assembly 84-185910. - All parts will be reconditioned except those parts listed in Paragraph 3.1.1.1 of this specification.

3.1.2.2. Engine Baffles Installation 189110. - All parts will be reconditioned.

3.1.2.3. Segment Assemblies 84-185880, 84-185881, 84-185882, 84-185883, 84-185884, 84-185885, and 84-185886. - All parts except those parts listed in Paragraph 3.1.1.2 of this specification will be reconditioned.

3.1.3. Parts to be Supplied New:

3.1.3.1. Engine Inner Cowling Assembly 84-185910. -

694-185896-2 Seal  
694-185896-4 Seal  
694-185910-38 Kearsarge strip  
694-185910-39 Kearsarge strip  
49389-1 Fastener  
S5-200 Dzus spring

|            |                       |              |   |                        |      |
|------------|-----------------------|--------------|---|------------------------|------|
| WRITTEN BY | <i>H. Fitzpatrick</i> | DATE ISSUED  | OVERHAUL SPECIFICATION                  |                        |      |
| PROJECT    |                       | 1-29-53      | INNER COWL, BAFFLES, AND ENGINE SEALS - |                        |      |
| ENGINEER   |                       |              | MODEL C-45G AND C-45H                   |                        |      |
| APPROVAL   | <i>J. J. Murphy</i>   | DATE REVISED | Beech Aircraft                          | OVERHAUL SPECIFICATION | PAGE |
| APPROVAL   |                       |              | CORPORATION                             | NO. 9811               | 3    |
| E-138A     |                       |              | WICHITA, Kansas                         |                        |      |

## OVERHAUL SPECIFICATION 9811

PAGE A OF 9

TITLE INNER COWL, BAFFLES, AND ENGINE SEALS - MODEL C-45G AND C-45H

ISSUED 4-29-53

WRITTEN BY T. R. Taylor

REVISED 1-20-54

3.1.3.2 Segment Assemblies 84-185880, 84-185881, 84-185882,  
84-185883, 84-185884, 84-185885, and 84-185886.

|           |      |
|-----------|------|
| 84-189010 | Seal |
| 84-185887 | Seal |
| 84-185888 | Seal |
| 84-185889 | Seal |
| 84-185890 | Seal |
| 84-185891 | Seal |
| 84-185892 | Seal |
| 84-185893 | Seal |
| 84-185894 | Seal |
| 84-185895 | Seal |
| 69-185899 | Seal |

3.2 Causes for Rejection. - The specific conditions listed below and damage or wear which cannot be corrected by one or more of the authorized repairs listed in Paragraph 3.4 of this specification is cause for rejection.

- (a) Scrap 84-185910 inner cowlings made from mild steel.
- (b) Scrap 84-185910 inner cowlings that will require more than 15 man-hours labor to recondition.
- (c) Scrap 84-185910 inner cowlings with damage to the carburetor shield cutout that cannot be repaired in accordance with Paragraph 3.4.1(d) of this specification.
- (d) Scrap segment assemblies that have segments that are badly corroded or that have cracks progressing inward from the outside edges.

3.3 Reconditioning Operations:

Revised Inspection  
OVERHAUL SPECIFICATION

ITEM REPAIRS, LUBRICATION, AND MAINTENANCE - PART 3.4.2 AND 3.4.3

REF ID: A-29-3

WRITTEN BY R. R. Taylor REVISED 2-13-53

3.3.1 Engine Frame Covering Assembly 63-157510..

- (a) Inspect for unsatisfactory conditions.
- (b) Clean in accordance with GS 7032.
- (c) Remove old paint.
- (d) Repair as necessary as authorized herein.
- (e) Install new seals, hardware strips, and new fasteners in accordance with Drawing 63-157510.

3.3.2 Engine Part Nos 157107, 157108, and 157109..

- (a) Inspect for unsatisfactory conditions.
- (b) Clean in accordance with GS 7032.
- (c) Repair as necessary as authorized herein.
- (d) Paint with black enamel (lacquer) in accordance with PS 570A.

3.3.3 Segment Assemblies 63-157510, 63-157511, 63-157512, 63-157513,  
63-157514, 63-157515, 63-157516, 63-157517..

- (a) Inspect for unsatisfactory conditions.
- (b) Clean in accordance with GS 7032.
- (c) Remove all seals as listed in Paragraph 3.1.1.2.
- (d) Remove solid carburetor and foreign material by buffing with a soft wire brush.
- (e) Repair as necessary as authorized herein.
- (f) Install new seals in accordance with Item 3.3.1.

3.4 Additional Requirements:

3.4.1 Engine Frame Covering Assembly 63-157510..

- (a) All cracks over 1 inch in length, except to the seal and carburetor outlet flanges, will be stop drilled with a No. 30 drill and a reinforcement added. The reinforcement shall

3.4.1 Engine Lower Cowling Assembly 84-155720,- (Continued)

(a) (Continued)

be of the same material as the part being patched and shall be formed to fit over heads and to match contour of the cow. Use AL57003 rivets spaced approximately  $\frac{3}{4}$ -inch. Maintain two rivet diameters edge distance.

- (b) Cracks in areas other than in beads, radii and flanges, of 1 inch or less in length, will be repaired by drilling or filling a round hole of sufficient diameter to clean out the crack. Install a flat plug to fit the hole. Flatten ears of the plug after installation.
- (c) Seal attaching flanges requiring repair will be reinforced with a strip of the same thickness and the same material as the flange. The strip will be  $\frac{5}{8}$ -inch wide and of sufficient length to extend 1-1/2 inches beyond the damaged area. Cut the strip to match the seal attaching flange radius. (Reference 11-1/2-inch radius). Attach with AL57003 rivets flushed on the surface to which the seal is attached. Space rivets approximately  $\frac{1}{4}$ -inch, maintaining two rivet diameters edge distance.
- (d) Carburetor cut-out flange holes, elongated beyond allowable tolerances (Paragraph 3.4.1), and flange and radius cracks will be repaired by adding a patch made from .023 stainless (18-8) steel. Elongated holes will be reinforced with a strip  $\frac{5}{8}$ -inch wide and of sufficient length to extend 1/2-inch beyond the damaged holes. Cracks will be patched with a reinforcement formed to the contour of the cow and of sufficient size to extend 1/2-inch beyond the limits of the crack. Place one row of AL57003 or AL54403 rivets, spaced 1-1/2-inch maximum -  $\frac{3}{8}$ -inch minimum, along all edges of the reinforcement. Maintain an edge distance of two rivet diameters. Rivets will be flush on the inside surface of the flange. Stop drill all cracks before installing reinforcement.
- e Any number of engine mount bolt holes that are cracked or damaged may be reinforced with .023 maximum thickness (18-8) stainless steel. The size of the reinforcement shall be sufficient to extend approximately 3 inches inward towards the segment radius from the inner edge of the mounting flange. The width shall be approximately equal to the length. Form reinforcement to fit cow contour. Rivet with AL57003 or AL54403 rivets spaced  $\frac{3}{4}$ -inch maximum -  $\frac{3}{8}$ -inch minimum. Place rivets in the mounting flange area on both sides that would interfere with mounting bosses.

| B. Inspection |         | Part Number<br>84-155720-53 | OVERHAUL SPECIFICATION   |      |   |
|---------------|---------|-----------------------------|--|------|---|
| Part          | Section |                             | MIL-C-1100, B7775, AND B7776 STANDARDS -<br>ENCL C-453 AND C-455 |      |   |
| INSPECTOR     |         | DATE APPROVED               | STANDBY SPECIFICATIONS   | PAGE |   |
| SUPERVISOR    |         |                             | STANDBY SPECIFICATIONS   | PAGE | 6 |

## OVERHAUL SPECIFICATION

PAGE 7 OF 10

TITLE INNER COOL. Baffles AND FUELING SEALS - MODEL C-450 AND C-45H

ISSUED 4-29-53

WRITTEN BY T. R. Taylor

REVISED 4-13-54

## 3.4.1 Engine Minor Cooling Assembly 84-185910-10. - (Continued)

- (f) Replace 84-185910-24 and -25 orifices that are damaged and corroded to the extent that repair is impractical. Remove orifices that are attached by spotweld by sawing around flush with the surface of the inner cowl segment. Install 694-185910-26 or 694-185910-27 orifice with AN470A13 rivets spaced approximately 3/4-inch. Remove orifices that are attached with rivets by drilling out rivets. Install 694-185910-26 or -27 orifice with AN470A13 rivets. Pick up old holes in inner cowl.
- (g) Mislocated stayplate sheet attachments in 84-185910-15 and 84-185910-17 stiffeners are to be relocated to latest drawing information. Add 1-3/8- by 3-inch flat strip or 1-3/8- by 3/4- by 3-inch angle reinforcement to each mislocated hole. Form to fit the cowl contour and angle. Center the reinforcement over the old holes. Attach with AN470A13 rivets spaced approximately 3/4-inch. Maintain 2 rivet diameter edge distance. Install new S5-200 Dus springs.
- (h) Segments with holes on or adjacent to webs will be repaired with OS 9811-1 plates as illustrated in Figure 1.
- (i) In cases where the cowl flap actuating rod rubs the edge of the hole in the inner cowl, the hole may be elongated a maximum of 1/4-inch to provide clearance. Install an S-104-22 metal grommet. If more than 1/4-inch elongation is necessary, the hole may be enlarged as required to provide sufficient clearance from the cowl flap actuating rod and reinforced with a doubler of 016 corrosion-resistant steel (18-8). Extend doubler approximately 3/4-inch beyond limits of hole and form to fit inner cowl. Attach doubler with AN456AC3 rivets spaced approximately 1 inch with 1 1/4-inch edge distance. Cut 1 5/16-inch diameter hole in doubler to align with cowl flap actuating rod.
- (j) Add OS 9811-2 and OS 9811-3 angle clips when necessary to reinforce cracks at lower ends of carburetor box cutout attaching flanges. OS 9811-2 and OS 9811-3 angle clips are identical to M3 CO 74744-4 and M3 CO 74744-2 respectively.

## 3.4.2 Engine Baffling 186107, 186108, and 186109. -

- (a) Baffles with extra holes that interfere with the required holes for the air ducts will be repaired by welding a plug in the holes. Make plugs from 615-0 aluminum alloy conforming to Specification QQ-A-327, Condition A. Cut to fit inside hole. Weld plug to baffle and fill all unused screw holes with weld metal. Use weld with Type I QQ-N-566 aluminum alloy welding rod. Remove excessive weld on forward surface.
- (b) Small cracks and ragged edges will be repaired by welding as stated above.

## OVERHAUL SPECIFICATION 9811

PAGE 8 OF 9

TITLE INNER COOLING BAFFLES, AND ENGINE SEALS - MODEL C-45G AND C-45HISSUED 4-29-53DRAWN BY R. TaylorREVISED 2-18-54

3.4.3 Segment Assemblies 84-185880, 84-185881, 84-185882, 84-185883, 84-185884, 84-185885, and 84-185886.

- (a) Cracks up to 3/16 inch in length on the edges of all segment holes will be stop-drilled with a No. 50 drill.
- (b) Extra holes up to 3/16-inch diameter will be plugged with 15470AD rivets.
- (c) All holes in segments except rivet holes that are damaged will not be rounded out to a smooth camour providing the hole is not elongated more than 1/8 inch.

**4. INSPECTION**

**4.1 General.** The parts will be inspected to the general acceptable quality standards of Overhaul Specification 7008 and the specific quality standards listed below.


**4.2 Acceptable Quality Standards:****4.2.1 Inner Cooling 84-185910.-**

- (a) The 84-185910 assemblies will be acceptable when the over-all width of the carburetor cutout does not exceed a maximum of 9-23/32 inches.
  - (b) Holes in the side flanges of the carburetor cutout may be elongated to 1/32 inch in any one direction, providing the width of the hole does not exceed .200.
  - (d) A maximum of two engine mount bolt holes ~~.463~~ <sup>.453</sup> on any one inner cow assembly may be elongated to ~~.531~~ <sup>.521</sup> without rework.
  - (e) Double and elongated attaching holes for the 694-185896-2 and 694-185896-4 seals are acceptable provided that the 40980-1 fasteners are secure.
  - (f) Discoloration resulting from heat and carbon is acceptable, providing it does not remain as a result of inadequate cleaning.
- Overhaul Specification 9811 supercedes the following:

OB 456979A  
MFB 78104  
MFB 78743

MFB 74744A  
MFB 78082

AD-S 901-1 HULL PLATE AND HULL STERN TO HULL  
CLIPS IN HULL AT 3-1/2-INCHES



| H. Fitzgerald |          | 3    | OVERHAUL SPECIFICATION |             |      |
|---------------|----------|------|------------------------|-------------|------|
| Project       | Customer | Date | Part No.               | Description | Page |
| AD-S          | 3        | 1968 | AD-S 901-1             | HULL PLATE  | 1    |
| AD-S          | 3        | 1968 | AD-S 901-1             | HULL PLATE  | 2    |