

TITLE

SPECIAL INSPECTION  
RELAY MOUNTING BOX  
GENERATOR WARNING LIGHTS

E.M. NO.  
12290

FILE CODE

EFFECTIVE  
IMMEDIATELY

111  
-71

PART NO.

21798

NEW TITLE

RELAY MOUNTING BOX

DWG. NO.

JOB NO.

COPIES TO

NO.

USE OF E.M.

DISPOSITION OF STOCK

SALVAGE

CONCESSION

STOP ORDER/RELEASE

NEW DRAWING

REVISED DRAWING

VARIATION

CONSULT NOTICE

USE AS NOTED

CHECK BLOCKS AFFECTED

NOT AFFECTED

USE TO DEPLETION

REWORK

SCRAP

AS NOTED

PARTS COMPLETED

PARTS IN PROCESS

TOOLING

RAW MATL.

INTERCHANGEABILITY AFFECTED

STRENGTH AFFECTED

YES

NO

YES

NO

**BREWER**

ORIGINATED BY

*A. Redmond*

D. A. W. PROJ. ENG.

*R. P. [Signature]*

D. A. W. INSPECTION

CUSTOMER'S ORDER NO.

CUSTOMER

RCAF

TYPE AIRCRAFT

EXPEDITOR 3

AIRCRAFT REGISTRATION NO.

DATE

MAY 157

DWG. CHANGE

YES

NO

DWG. CONT.

YES

NO

APPROVALS

*[Signature]*  
ENGINEERING

*[Signature]*  
CONTRACTS ADMIN.

*[Signature]*  
SUPERVISOR

GIVE FULL PARTICULARS AND SKETCH WHERE POSSIBLE

IT HAS BEEN FOUND THAT THE RELAY MOUNTING BOX, P/N 21798 INSTALLED IAW EO OS-453-6A/66, MAY HAVE WATER IN IT.

THIS CONDITION WILL BE INSPECTED FOR ON ALL A/C AND ALL RELAY BOXES, P/N 21798, WILL BE DRILLED .1875" AT EACH AFT CORNER.

NOTE.

ABOVE CONDITION HAS BEEN FOUND ON A/C 2315 WHERE THE BOX WAS 3/4 FULL.

1766/2000/100/MAY 68

111-MAY-6-1957

Released May 6/57

NOTE: WHEN EFFECTIVITY IS OMITTED FROM E.M. CHANGES ARE TO BE EFFECTIVE UPON PLANNING DEPARTMENT AUTHORIZATION.