

ENGINEERING MEMORANDUM

TITLE Clarification - Cylinder Thermocouple Lead Attachment				E.M. NO. 12406		FILE CODE 111⁰⁰		
				EFFECTIVE Immediately		63		
PART NO.		PART NAME		DWG. NO.		COPIES TO		
				JOB NO.		NO.		
USE OF E.M.		DISPOSITION OF STOCK		CUSTOMER'S ORDER NO.		ENG.		
SALVAGE		CHECK BLOCKS AFFECTED	NOT AFFECTED	UP TO COMPLETION	REWORK	SCRAP	AS NOTED	
CONCESSION								
STOP ORDER/RELEASE		ORIGINATED BY		CUSTOMER		INSPEC		
NEW DRAWING		PARTS COMPLETED	<i>H. Anderson</i> E. A. W. PROJ. ENG.		RCAF		PROD.	
REVISED DRAWING		PARTS IN PROCESS					PLANNING	
VARIATION		TOOLING	<i>R. Latoch</i> A. W. INSPECTION		Expeditor 3		MAT. CONT.	
OBsolete NOTICE		RAW MAT'L					CONT. ADM.	
USE AS NOTED	<input checked="" type="checkbox"/>	INTERCHANGEABILITY AFFECTED	DATE		AIRCRAFT REGISTRATION NO.		ESTIMATING	
		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	15 Aug 57		COWTAN 1		DWG. CHANGE	
APPROVALS				DWG. CORRT.		4		
		<i>H. Anderson</i> ENGINEERING		<i>C. L. ...</i> CUSTOMER				

Some doubt exists as to the correct location of the Thermocouple Leads on the AN985-AN14B engines on Expeditor Aircraft.

This EM is issued to advise that the correct location for the Thermocouple Leads is on #9 cylinder on the RH engine and on #2 cylinder on the LH engine.

This information will be incorporated in the next revision to EO 05-45B-2.

Ref. AMC letter 1038JU-3 (SACO/ACR2-1) of July 10, 1957.