

TITLE <u>REPAIR SCHEME</u> <u>FIRE EXTINGUISHER CABLE</u>		E.E.P. NO. 12587		FILE CODE 111-83
EFFECTIVE IMMEDIATELY		DWG. NO. 111-83003 B		COPIES TO NO.
PART NO. UNK		PART NAME FIRE EXTINGUISHER CABLE		NO.
USE OF E.E.P.		DISPOSITION OF STOCK		NO.
SAVAGE	<input checked="" type="checkbox"/>	ORDER BLOCKS AFFECTED	NOT AFFECTED	3
CONCESSION		USE TO EXPLANATION	REWORK	6
STOP ORDER/RELEASE		AS ORDERED		9
NEW DRAWING		ORIGINATED BY BREWSTER		2
REVISED DRAWING		CUSTOMER RCAF		2
TERMINATION		TYPE AIRCRAFT EXPEDITE 3		1
COMPLETE NOTICE		AIRCRAFT REGISTRATION NO.		3
NOTE AS NOTED		DATE 2 APR 58		1
APPROVED		DATE		DWG. CHANGE
<i>[Signature]</i>		2 APR 58		YES NO
ENGINEER (I)		CONTRACTS ADMIN.		DWG. CONT.
<i>[Signature]</i>		<i>[Signature]</i>		4
GIVE FULL PARTICULARS AND SKETCH WHERE POSSIBLE		CUSTOMER		
		<i>[Signature]</i>		

WHEN THE CABLE ATTACHING TO THE FIRE EXTINGUISHER PULL HANDLE NEEDS REPLACEMENT THE PROCEDURE SHALL BE AS FOLLOWS:

- a) IF THE HANDLE IS OF THE TYPE SHOWN IN FIG 1, THE CABLE IS TO BE REPLACED IAW DWG 111-83003,
- b) IF THE HANDLE IS OF THE TYPE SHOWN IN FIG 2, THE CABLE IS TO BE REPLACED AS SHOWN IN FIG. 3, THE LENGTH OF THE TO BE 43", EXACT LENGTH BEING DETERMINED UPON ASSEMBLY.

NOTE: COMPLETE HANDLE & CABLE ASS'Y - KIDDE PT. NO. 908810



FIG 1




FIG 2



FIG 3

DWM/BAW/SM/DAV 58

PLAN - APR - 3 - 1958

NOTE: WHEN EFFECTIVITY IS OBTAINED FROM E.E.P. CHANGE; AND TO BE EFFECTIVE UNLESS PLANNING DEPARTMENT AUTHORIZATION.