

TITLE

Repair to Fuselage Tail Section - Expeditor 1598

E.M. No.

12593

2.6

Replace skin reinforcements on tail lifting
bar cut outs.

2.7

Items removed, tail wheel truss assembly, fork
assembly and truss bearings are to be inspected for cracks,
alignment or other defects prior to re-installation.

As this work is over and above C.A.I.R., it is to be
carried out on F.W.A.