


TITLE CARBURETTOR HEATER MUFFS - INSTALLATION.		U.S. NO. 12800		FILE NO. 111 -51
PART NO. BEECH 105798		PART NAME CLAMP-SHELL ASS'Y		COPIES TO
USE OF E.D.		DISPOSITION OF STOCK		COPIES TO
RELEASE		CHECK CHECKS AFFECTED	NOT AFFECTED	5
ORDINATION		LINE TO EXPLANATION	DATE	6
STOP ORDER/RELEASE		AS NOTED		7
NEW DRAWING		BREWER ORIGINATED BY A. Johansen D. A. W. PROJ. ENG.		PLANNED
REVISED DRAWING		J. Juzak D. A. W. INSPECTOR		2
VARIATION		CUSTOMER'S ORDER NO. RCAF		2
OBsolete NOTICE		TYPE AIRCRAFT EXP 3		1
USE AS NOTED	<input checked="" type="checkbox"/>	AIRCRAFT REGISTRATION NO. 1928/59		3
		DATE 1928/59		1
		D.W. CHANGE YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		3
APPROVALS		S. Taylor F.S. CUSTOMER		

ONE FULL PARTIAL AND EXISTING QUANT POSSIBLE

MARMAN CLAMP PIN 820-18 MAY BE USED INTERCHANGEABLY WITH BEECH CLAMPS PIN 105798 -10, -14, -17, -18 & -21 FOR THIS INSTALLATION, AS REQUIRED.

THE CLAMP SHOULD BE TRIMMED IN LENGTH TO SUIT.

DRILL 1/16" HOLE IN HANDLE ~~AS SHOWN~~ AS SHOWN.



6
4
1/16 + 1/8
- 0

J. Juzak 2/29/59

0102/SAW/18/10/1959