

TITLE <b>"CLICKING SOUND" - ENGINE CONTROLS</b>		FILE NO. <b>12779</b>	FILE CODE <b>111</b>
		SUBJECT <b>Immediately</b>	<b>-42</b>
PART NO.	PART NAME <b>ENGINE CONTROL</b>	ENGINE NO.	ORDER TO
USE OF E.M.	DISPOSITION OF STOCK:	CUSTOMER'S ORDER NO.	ENCL.
SALVAGE	CHECK BLOCKS AFFECTED	CUSTOMER <b>R.C.A.F.</b>	IMPED.
CONDEMN	NOT AFFECTED	TYPE AIRCRAFT <b>EXPEDITOR 3</b>	PROD.
STOP ORDER/RELEASE	USE TO DELISTION	AIRCRAFT REGISTRATION NO.	PLANNING
NEW DRAWING	NETWORK	DATE <b>5/14/59</b>	EST. CONT.
REVISED DRAWING	REWORK	OWG. CHANGE YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	SALES/CONTS
VARIATION	REPAIR	OWG. CONT.	R.O.A.F.
OBsolete NOTICE	AS NOTED		ESTIMATING
USE: AS NOTED	INTERCHANGEABILITY AFFECTED		TEST FLIGHT
	STRENGTH AFFECTED		
APPROVALS	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		

ORIGINATED BY  
*H. Richardson*  
B. A. W. PROJ. ENG.

*E. Duzak*  
B. A. W. INSPECTION

APPROVALS  
*[Signature]* ENGINEERING  
*[Signature]* CONTRACTS ADMIN.  
*[Signature]* CUSTOMERS


GIVE FULL PARTICULARS AND SKETCH WHERE REQUISITE

Cases occur where a "clicking sound" can be heard when an engine control is moved in alternate directions.

This sound occurs when the inner solid wire moves relative to outer spiral surrounding the wire.

This condition is acceptable.

Abnormal noise, play or other defects are still cause for rectification or rejection.



NOTE: WHEN EFFECTIVITY IS OBTAINED FROM E.M. CHANGES ARE TO BE EFFECTIVE UPON PLANNING DEPARTMENT AUTHORIZATION.

May 20/59