

TITLE

INSPECTION & REPAIR OF SPINNER RING
(CONT'D).

E.M. No.

12891

SHT. 2

MANUFACTURE OF NEW DOUBLERS:

IT IS APPARENT ALL CRACKED DOUBLERS HAVE
EXTENSIVE CRACKS & CAN NOT BE SALVAGED.

