

## ENGINEERING MEMORANDUM

TITLE	ADDITIONAL SUPPORT - WINDSHIELD COWL COMPASS MOUNT AS PER FIG. 1.		REF. NO. 12963	DATE 11/1/- 63
PART NO.			END PG. 1	END PG. 2
ITEM NO.			END PG. 3	END PG. 4
TYPE OF COWL	DISPOSITION ON STORE		CARRIERS STORED IN:	
COWL/SCREEN	UNFITTED	REFURBED	UNFITTED	UNFITTED
COMPONENT	REFURBED	REFURBED	REFURBED	REFURBED
ITEM GROUP/TESTES	ITEMS TESTED OR EXAMINED BY		CARRIER	
ITEM DRAWING	Y. H. L. S. AND D. W. D. A. W. P. & D. E. G.		RCAF	
REVISED DRAWINGS	PARTS IN PROGRESS		TYPE AIRCRAFT	
VARIATION	TOOKED		EDITOR	
COMPLETE NOTES	NEW DATE		AIRCRAFT INSPECTION NO.	
ITEM AS NOTED	✓	INTERMAGNETICITY TESTED	MAX. 60	TEST FLIGHT
APPENDIX	YES	NO	YES <input checked="" type="checkbox"/>	NO
NOTE: PART NUMBER AND SERIAL NUMBER UNKNOWN				
REMARKS: CARRIER WITH 67. DISPOSITION UNKNOWN.				

THE MAGNETIC COMPASS (RCAF REF. 6B/669)  
HAS BEEN REPORTED TO VIBRATE FREELY  
ON SOME AIRCRAFT DURING FLIGHT.

TO RECTIFY THIS CONDITION THE  
WINDSHIELD COWL IS TO BE GIVEN ADDITIONAL  
SUPPORT BY INSTALLATION OF THE BRACE, SHOWN  
IN FIG. 2, AS PER FIG. 1.

THIS INST ALLATION IS OVER TO BE  
MADE ON AIRCRAFT SNAGGED FOR EXPRESSIVE  
VIBRATION OR THE MAGNETIC COMPASS.

NOTE: TO BE CARRIED OUT ON R.C.A.F. PHOTOCOPIES.

# ENGINEERING MEMORANDUM

TITLE      ADDITIONAL SUPPORT -  
              WINDSHIELD COMPASS MOUNT

E.M. No. 12963





FIG. 1

THIS END TO ATTACH TO THE 404-183752 BRACKET.

DRILL #11 (.191)  
1 HOLE TO FIT



NOTE: SEND ENDS AS REQ'D  
TO FIT.

MATERIAL:  $\frac{3}{8}$ " X .035" STS  $\frac{1}{2}$  HARD  
ALUMINUM TUBE

FIG. 2