BRISTOL AERO-INDUSTRIES LIMITED

ENGINEERING MEMORANDUM

4/0/h

TIME ENGINE MOUNT					W/E	BLY	SI	PARES	14028			A	FILE 11:	
CLARIFICATION OF COMPONENTS									EFFECTIVE ENTED LATE			-51		
PART NO. PRAT PLANE							-		DWR. 603.	265.		A-ACTI B-INFO	0346	
1839100-29	Eng	ine	9 M	ou	at	As	emply	W/0 NO.			70	A	1 8	
REASON FOR ISSUE				DESTRON OF STOCK					OUSTONERS ORDER NO		11	memore	-	
SALVAGI		CHICCH	0	Mescalen	1	-	10		CUSTOMEN FCAP		1	No		2
CONCRESION	-		107	UER TO	MEWORK	SCRAP	101E				B	PROG.		-
STOP ORDER/RELEASE	-	APPECTED	APPEOT UER T	35			8	ORIGINATED BY			R	gr,J,mo		-
NEW DRAWING	-	PARTS COMPLETED						in D	TYPE OR LEDOSL	-	8		-	-
REVISED BRAYERDS		PARTS IN PROCESS					-	MRIT	TXTTDITOR		- Contract	PLANSY'S	-	1
VARIATION		TOGLENG						DAIL PROJ. ENG.	ARCHAPT REGISTRATION NO.	-	-	MJF. 13	- HOUSE-HOUSE	-
CECCLETE SCITCE		JEAN SEAT'L						1 6:11	A ALL		_	TEM AL	7	1
LINE AS STOPED	x	S SPITEMENANCEABILITY STRENGTHS APPRINTED APPRINTED YES NO YES 500				11.11.WW	The state of the s			GUPT.		-		
					V25 10			BAIL INSP.	Divide Green		MANUF. SUFF.		-	-
Ozmana MV manamed				A CONTRACTOR OF THE PARTY OF TH	-0	-/	~	ealer .	1 1 1			PRETION		- Company
ENDAMERRING				6	6	CONT			Stand wo			A.F.		1
CIVE PULL PARTICULARS AND EXCEPT WISERE PRODUCE.										- Common	TOST PLINNT		- Civilla	The state of the s
								-	CLASTOAGES	3	-450	L OGNITROL		1
								Веспецияния			-			

The Expeditor parts book now calls up 183 9100-29 for the spares engine mount assembly. Some clarification of the components of the -29 is necessary. These were listed in T.R 2573, STR 40, page 1, where Bristol suggested that the -29 assembly be numbered -606 for spares purposes. However, this was not approved by the RCAF and the only spares assembly is still -29 and the components are as follows:

186 9100-28 - Welfed mount assembly - 1 required J = 5384-1 - Bushing (Lord mount) - 1 required J = 5385-1 - Bushing (Lord mount) - 2 required 404-189102 - Bonding strips - 3 required AN4-4A - Bolt - 3 required AN960-416 - Washer - 3 required M520365-428 - Wut - 3 required

Engine attachments and truss attachments do not form part of the -29 assembly.

Mount assemblies received for overhaul as 183 9100 should be reworked as above and re-identified as 1839100-29 assemblies.

221