


TITLE <b>REPLACEMENT OF BENDIX ADF SENSE ANTENNA WIRE &amp; FITTINGS</b>		E.M. NO. <b>15999</b>	ISSUE <b>A</b>	FILE CODE <b>112-</b>	
		EFFECTIVE <b>IMMEDIATELY</b>		<b>72</b>	
PART NO.	PART NAME	DWG. NO.	ISS.	DISTRIBUTION A-ACTION S-INFORMATION	
		W/O NO.		TO A B	
REASON FOR ISSUE		DISPOSITION OF STOCK		CUSTOMERS ORDER NO.  CUSTOMER <b>SHERRITT -GORDON</b> TYPE OR MODEL  AIRCRAFT REGISTRATION NO. <b>CF-NUY</b> DATE <b>15 AUG 69</b> DWG. CHANGE YES <input type="checkbox"/> NO <input type="checkbox"/>	
SALVAGE	CHECK BLOCKS AFFECTED	NOT AFFECTED	USE TO DEPLETION		DESIGN
CONCESSION					A/C
STOP ORDER/RELEASE					PROD.
NEW DRAWING	PARTS COMPLETED				EL'T'NG
REVISED DRAWING	PARTS IN PROCESS				A/C PLANN'G
VARIATION	TOOLING				MANUF. "
OBSOLETE NOTICE	RAW MAT'L				MATERIAL
USE AS NOTED	INTERCHANGEABILITY AFFECTED	STRENGTH AFFECTED			A/C SUPT.
	YES <input type="checkbox"/> NO <input type="checkbox"/>	YES <input type="checkbox"/> NO <input type="checkbox"/>			SALES/CONT.
APPROVALS	M.E. <b>Thompson</b> ORIGINATED BY  M.E. <b>Thompson</b> BAIL. PROJ. ENG.  H.A. <b>Curry</b> BAIL. INSP.		INSPECTION R.C.A.F. TEST FLIGHT DWG. CONTROL		
GIVE FULL PARTICULARS AND SKETCH WHERE POSSIBLE		CUSTOMER			
		CUSTOMER			

1. Remove the following sense antenna components from the underside of the aircraft.

- (a) porcelain feed thru' insulator
- (b) fwd. insulator-tension unit, aft insulator and interconnecting wire.

2. Install new components as per sketch



**JIM JACK JOHN**  
**DES FILE**  
**BOB TOM MAL**