## DESCRIPTION AND MAINTENANCE INSTRUCTIONS

## SPARK PLUGS & MAGNETOS APPROVED TYPES FOR RCAF ENGINES

(This EO replaces EO 15-5F-2C dated 30 Nov 54)

l The spark plugs listed are not in order of preference. In any one engine all spark plugs installed are to be of the same type.

are maintained as a complete set. Unserviceable or incomplete sets are to be reported in accordance with CAP 16, Vol. 1, Sec. Q13/1.

2 Spark plugs are to be changed at periods detailed in the relevant aircraft maintenance schedules.

Engine USAF Approved Spark Plugs

3 Aircraft deliveries from the USAF may have spark plugs installed that are not listed in this Engineering Order. However, if these plugs are authorized by the USAF, they may be accepted and are to be used provided they

Wright GR 2600 LS88RC 35 S SL 2 K

P&W R985 RC26S 706 SR SH 2 K

P&W R1340 RC26S 706 SR SH 2 K

ENGINE	REF.	SPARK PLUG	GAP	REF.	MAGNETO
Rolls Royce Merlin 620/622	<b>375/</b> 16	Lodge LR 3R	.018 to .020	37A/5301	Rotax NSE
			4	/5302	12/5C
Packard	37S/17	Lodge RS5/7	.018 to .020	37A/5299	BTH C6SE 12S
Merlin V.650-7				/5300	,
				37A/5301	Rotax NSE 12/9C
				/5302	
				37A/5917	Rotax NSE 12/7C
				/5918	
Packard	37S/17	Lodge RS5/7	.018 to .020	37A/52.99	BTH C6SE 12S
Merlin 224/225	375/14	KLG RC5/3	.018 to .020	/5300	
				37A/5917	Rotax NSE 12/7C
, **	,			/5918	
				37A/5301	Rotax NSE 12/9C
*				/5302	



ENGINE	REF.	SPARK PLUG	GAP	REF.	MAGNETO
					WIAGNETO
Wright 1820-84	37S/163	Champion R103	.015 to .018	37A/1255	Scintilla
		(3/4 screen tube thread)			D9LN-3
Wright 1820-103	37S/13	Champion R37S-1	.013 to .016	37A/1243	Bosch S9LU-3
Wright GR 2600 (all series)	378/25	Lodge RS19/2R	.012 to .015	37A/5631	Scintilla
	37S/13	Champion R37S-1	.013 to .016		SF 14LN-3
Wright 3350-85	37S/158	Champion R33S (5/8 screen	.015 to .018	37A/859	Scintilla
		tube thread)			DLNy
	375/163	Champion R103 (3/4 screen tube thread)	.015 to .018		
Pratt & Whitney	375/22	Champion	.012 to .015	37A/1141	Scintilla
R985 (all series)		C26S	)		SB 9RN
				37A/4004	Bosch
					SB9RU-3
Pratt & Whitney R1340, -AN1,	375/22	Champion	.012 to .015	37A/1141	Scintilla
-S3H1, -S3H1G		C26S			SB9RN
Pratt & Whitney R:340 - S1H2	37S/22	Champion	.012 to .015	37A/1237	Scintilla
		C26S			SB9RN-4
Pratt & Whitney R:830	37S/25	Lodge RS19/2R	.012 to .015	37A/1180	Scintilla
(all series)					SF 14LN-3
	37S/13	Champion R37S-1	.013 to .016	37A/4183	Bosch SF 14LU-7
Pratt & Whitney R2800 - CA15	37S/13	Champion R37S-1	.013 to .016	37A/1262	Scintilla
					DLN 10
ė		v.			

ENGINE	REF.	SPARK PLUG	GAP	REF.	MAGNETO
Hercules 734	<b>3</b> 7S/157	Lodge LB3/2	.012 to .015	37A/1263	Rotax
	37S/162	Lodge LB 3/3	.008 to .010		N14A/1
	37S/181	KLG KB3	.008 to .010	SI .	
Franklin 6V4-200-C32	37S/174	AC LA-47	.015 to .018	37A/1232	S6RN-23
Gypsy Major Shielded	<b>37S</b> /6	KLG RV12/3	.012 to .015	37A/5298	BTH AG4-10
Harness	375/9	Lodge RS50-R		37A/5906	BTH AG4-12
Continental 0-470-11	375/22	Champion C26S	.012 to .015	37A/1241	Scintilla
				,	S6LN-21
Continental 0-470-13	37S/22	Champion C26S	.012 to .015	37A/1238	Scintilla
V-#1U-13					S6LN-23

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF