

DESCRIPTION AND MAINTENANCE INSTRUCTIONS

SOCKET ASSEMBLY - LANDING GEAR DOOR INSTALLATION

INFORMATION

1 Previously when the bushing in the socket assembly Ref. 3MBA4288-50L or -50R was found upon inspection to be worn beyond limits the whole assembly would have to be changed. This socket assembly is difficult to change because it has to be bent out of shape for installation and reformed around the strut, see EO 05-45B-4, Figure 8. To remedy this, bushings Part 3MBA4288-55 are being supplied separately thus saving material and man-hours because the undercarriage doors do not have to be rigged after installation.

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF

[Faint, illegible stamp]

Prepared By:
AMC/SACO/ACR