EO 10A-10AA-5A

ROYAL CANADIAN AIR FORCE



LIST OF SPECIAL INFORMATION

WASP R985-AN1, -3, -6B AND
-14B ENGINES

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF

TABLE OF CONTENTS

LATEST DATE

EO NUMBER

TITLE

19 Nov 53

10A-10AA-5A/1

Visual Inspection of Nose Section Thrust Nut for Oil Leakage ROYAL CANADIAN AIR FORCE

EO 10A-10AA-5A/1 19 Nov 53

COPY

SPECIAL INFORMATION

VISUAL INSPECTION OF NOSE SECTION THRUST NUT FOR OIL LEAKAGE

- l Several cases of cracking of the crankshaft in the thrust nut threaded area on Pratt and Whitney R985-AN14B engines have been reported.
- When oil leakage at the nose section is found, a thorough inspection for source of leak is to be made. Where the oil leak is from the thrust nut area on the crankshaft, the engine is to be removed and disposal requested.

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF



Prepared By: AMC/SACO/ACR