

TRAINING COMMAND

TECHNICAL INSTRUCTIONS

EXPEDITOR AIRCRAFT

ANTI ICER PUMP -

MODEL CLARIFICATION

TCTI D4/4
1 Jan 59

- 1 A number of Expeditor aircraft are known to have anti icer pump reference 37J/8 installed in lieu of the correct type pumps reference 37J/7 or 37J/11.
- 2 Pump 37J/8 has a larger capacity than 37J/7 or 37J/11 and is intended for use on a different type aircraft, and while it has proved to operate satisfactory on Expeditors due to calibration of rheostat governing and restricting its output, continued use of this pump would result in a shortage on aircraft for which it was intended.
- 3 To prevent shortage noted in para 2 developing, pump 37J/8 installed on Expeditor aircraft are to be replaced at time expiry or when they become u/s by the correct type pump reference 37J/7 or 37J/11.
- 4 This TCTI replaces TCHQ message AE390 dated 10 April 1958.
- 5 A copy of this TCTI is to be inserted in front of EO 05-45B-2 in the appropriate EO binder.