BRISTOL AIRCRAFT (WESTERN) LIMITED
WINNIPEG CANADA

ENGINEERING MEMORANDUM

TITLE: RELOCATION LOCALISER Rx BC 733
REF EO 05-45B-6A/130.

E.M. NO.: EM 12877
FILE CODE: 111-21
EFFECTIVE: IMMEDIATELY
DWG. NO.:
JOB NO.:
CUSTOMER'S ORDER NO.:
CUSTOMER: RCAF
TYPE AIRCRAFT: EXPEDITOR 3NMT
AIRCRAFT REGISTRATION NO.: 1594 1507
DATE: Oct 6/59
DWG. CHANGE: YES X

PART NO.:
PART NAME:

USE OF E.M.	
SALVAGE	
CONCESSION	
STOP ORDER/RELEASE	
NEW DRAWING	
REVISED DRAWING	
VARIATION	
OBSOLETE NOTICE	
USE AS NOTED	

DISPOSITION OF STOCK

CHECK BLOCKS AFFECTED	NOT AFFECTED	USE TO DEPLETION	REWORK	SCRAP	AS NOTED
PARTS COMPLETED					
PARTS IN PROCESS					
TOOLING					
RAW MAT'L					

INTERCHANGEABILITY AFFECTED: YES / NO
STRENGTH AFFECTED: YES / NO

ORIGINATED BY: G. Tuck
B. A. W. PROJ. ENG.: [signature]
B. A. W. INSPECTION: [signature]

COPIES TO	NO.
ENG.	5
INSPED	6
PROD.	9
PLANNING	2
MAT. CONT.	2
SALES/CONT'S	1
R.C.A.F.	3
ESTIMATING	1
TEST FLIGHT	2
DWG. CONT.	3

APPROVALS: [signature] ENGINEERING; [signature] CONTRACTS ADMIN.; [signature] CUSTOMER

GIVE FULL PARTICULARS AND SKETCH WHERE POSSIBLE

The localiser Rx BC 733 will be reinstalled in the "as received" position regardless of fouls.

Inspection department will make the following L-14 entries

① "The 2nd Right Hand reclining cabin seat is NOT to be used until the existing fouls occasioned by conversion to 3NMT configuration in accordance with EO 05-45B-6A/130 are corrected by AMCHQ action BRISTOL UCR 9912/A50 DATED 6 OCT/59 REFERS."

② "The localiser Rx fouls the navigator seat lug at its chassis and occupancy of the reclining seat causes a foul on top of the localiser Rx.

Oct 6/59

NOTE: WHEN EFFECTIVITY IS OMITTED FROM E.M. CHANGES ARE TO BE EFFECTIVE UPON PLANNING DEPARTMENT AUTHORIZATION.

SHEET 1 OF 1 SHEETS