

ENGINEERING MEMORANDUM

TITLE AGE LIMITS OF HOSES		E.M. NO. 12086	FILE CODE 000 -60
EFFECTIVE Immediately			
PART NO.	PART NAME	DWG. NO.	COPIES TO NO.
USE OF E.M.		JOB NO.	ENG. 2
DISPOSITION OF STOCK		CUSTOMER'S ORDER NO.	INSPEC 6
SALVAGE	CHECK BLOCKS AFFECTED	CUSTOMER R.C.A.F.	PROD. 9
CONCESSION	NOT AFFECTED	PLANNING	2
STOP ORDER/RELEASE	USE TO DELETION	MAT. CONT.	2
NEW DRAWING	REWORK	TYPE AIRCRAFT All	CONT. ADM. 1
REVISD DRAWING	SCRAP	AIRCRAFT REGISTRATION NO.	R.C.A.F. 3
VARIATION	AS NOTED	DATE 180-156	ESTIMATING 1
OBSELETE NOTICE	TOOLING	DWG. CHANGE	Purch 1
USE AS NOTED	RAW MAT'L	YES <input type="radio"/> NO <input checked="" type="radio"/>	DWG. CONT. 3
INTERCHANGEABILITY AFFECTED		APPROVALS	
STRENGTH AFFECTED		GIVE FULL PARTICULARS AND SKETCH WHERE POSSIBLE	
YES <input type="radio"/> NO <input checked="" type="radio"/>	YES <input type="radio"/> NO <input checked="" type="radio"/>	ENGINEERING: <i>[Signature]</i> CONTRACTS ADMIN: <i>[Signature]</i> CUSTOMER: <i>[Signature]</i>	

The following is extracted from a letter of AMC letter file 10330-3 (CQC) dated 14 Aug/56.

- (a) The age limit of 4 quarters stated in para 3.8 of MIL-H-5511A applies to hose and to hose assemblies supplied by hose manufactureres or hose couplers or their agents.
- (b) The age limits of MS 28741 apply to hose assemblies supplied to any government service by aircraft, engine or accessory manufacturers, or repair contractors. Therefore, assemblies from these sources are acceptable if the hose is not over 6 quarters old.

This is a clarification of the conflict between the age limit clauses of specification MIL-H-5511 and drawing MS28741.