

ENGINEERING MEMORANDUM

TITLE PROPELLOR GOVERNOR CONTROL ASS'Y		E.M. NO. 12308	FILE CODE 111 42												
PART NO. 1859022-6	PART NAME FORK ASS'Y	DWG. NO.	COPIES TO NO.												
USE OF E.M.	DISPOSITION OF STOCK	CUSTOMER'S ORDER NO.	NO.												
SALVAGE	<table border="1"> <tr> <th>CHECKED BLOCKS AFFECTED</th> <th>NOT AFFECTED</th> <th>USE TO DEFLECTION</th> <th>NETWORK</th> <th>SCRAP</th> <th>AS NOTED</th> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>	CHECKED BLOCKS AFFECTED	NOT AFFECTED	USE TO DEFLECTION	NETWORK	SCRAP	AS NOTED							INSPEC	NO.
CHECKED BLOCKS AFFECTED		NOT AFFECTED	USE TO DEFLECTION	NETWORK	SCRAP	AS NOTED									
CONCESSION		BEWER ORIGINATED BY <i>H. K. ...</i> S. A. W. ... ENG.	CUSTOMER RCAF	PLANNING	NO.										
STOP ORDER/RELEASE			TYPE AIRCRAFT EXPENDERS	MAT. CONT.	NO.										
NEW DRAWING			AIRCRAFT REGISTRATION NO.	CONT. ADM.	NO.										
REVISED DRAWING			DATE	ESTIMATING	NO.										
VARIATION	DWG. CHANGE														
OSOLETE NOTICE	DWG. CONT.														
USE AS NOTED	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>														
APPROVALS	<i>[Signature]</i> ENGINEERING	<i>[Signature]</i> CONTRACTS ADMIN.	<i>[Signature]</i> CUSTOMER												

GIVE FULL PARTICULARS AND SKETCH WHERE NECESSARY

REF: EO 05-45B-5/68

1. TO ELIMINATE WEAR OF BOLT P/N 4-189036 IN FORK ASS'Y P/N 1859022-6 THE FORK ASS'Y IN SOME CASES IS FOUND DRILLED OVERSIZE & A FIELD MANUFACTURED BUSH INSTALLED.
THIS IS ACCEPTABLE.
2. FOR REPAIR OF WEAR AT BAW THE BOLT WILL BE REPLACED.
- 3 THE BUSHINGS DESCRIBED IN 1 ABOVE WILL NOT BE REMOVED.

756/BAW/AM/ASSY 49
RUN - AUG - 6 - 1957