

ENGINEERING MEMORANDUM

TITLE RUDDER CABLE IDLER PULLEY-EXP. 1422		E.M. NO. 12665	FILE CODE 111-41
PART NO. 2MBA13524		EFFECTIVE EXP. 1422	
PART NAME PULLEY ASSY.		DWG. NO.	COPIES TO NO.
USE OF E.M.		JOB NO.	ENG. 3
SALVAGE	DISPOSITION OF STOCK	CUSTOMER'S ORDER NO.	INSPEC 6
CONCESSION ✓			PROD. 9
STOP ORDER/RELEASE	CHECK BLOCKS AFFECTED	CUSTOMER R.C.A.F.	PLANNING 2
NEW DRAWING	NOT AFFECTED	TYPE AIRCRAFT EXP. 3T	MAT. CONT. 2
REVISED DRAWING	USE TO DEPLETION	AIRCRAFT REGISTRATION NO. 1422	SALES/CONT'S 1
VARIATION	REWORK	DATE 7/9/58	R.C.A.F. 3
OBSOLETE NOTICE	SCRAP	DWG. CHANGE YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	ESTIMATING 1
USE AS NOTED ✓	AS NOTED	TEST FLIGHT	1
APPROVALS		DWG. CONT. 4	
GIVE FULL PARTICULARS AND SKETCH WHERE POSSIBLE		DWG. CONT. 4	

IN ORDER TO RECTIFY INTERFERENCE BETWEEN THE RUDDER CABLE AND WOBBLE PUMP ELBOW, AN IDLER PULLEY IS TO BE INSTALLED AS SHOWN ON DWG. 4MBA13483.

THIS EM APPLIES TO EXPEDITOR 1422 ONLY

CANCELLED

B. David Brewer
24 Sept 58

SEP 24 1958