

TITLE SAFETY MARKINGS - AIRCRAFT INTERIOR - EMERGENCY EXITS		REV. NO. 12723	PLAT. CODE 111-84
DEPT. NO.	PART NAME	DATE	COPIES TO
USE OF RES.		CUSTOMER'S ORDER NO.	ENG.
SALVAGE	DISPOSITION OF STOCK	CUSTOMER	ENGRS.
CONDITION	CHECK STOCKS AFFECTED	BCAF	FEED.
STOP ORDER/RELEASE	ANY AFFECTED	TYPE APPROVAL	PLANNING
NEW DRAWING	PARTS COMPLETED	EXPEDITOR 3	MAT. CONT.
REVISED DRAWING	PARTS IN PROCESS	AIRCRAFT REGISTRATION NO.	SALES/CONT'S
VARIATION	TUGGING	DATE	R.O.A.F.
DISCRETE NOTICE	RAW MAT'L	2002/28	ESTIMATING
USE AS NOTED	INTERCHANGEABILITY AFFECTED	DWG. CHANGE	TEST FLIGHT
	YES <input type="radio"/> NO <input checked="" type="radio"/>	YES <input type="radio"/> NO <input checked="" type="radio"/>	DWG. CONT.
APPROVALS	<i>A. Macdonald</i>	<i>W. J. ...</i>	<i>A. ...</i>

ON ALL EXPEDITOR 3TM'S & ON ALL A/C WHICH REQUIRE RENEWAL OF BEADING AROUND THE EXITS, RED GARMENT LEATHER WILL BE USED TO COVER THE BEADINGS INSTEAD OF RED PAINT TO GIVE MARKINGS IAW EO 05-1-20.

OCT 28 1958

*Latoock
Shuttleworth 9
File -*

Oct 26/58