

**DESCRIPTION AND MAINTENANCE INSTRUCTIONS**  
**PAINTING OF THE UPPER RING COWLING**  
**ON EXPEDITOR AIRCRAFT**

**INTRODUCTION**

1 Previously only the inner half of the upper ring cowlings on the Expeditor engines were painted matt black. This prevented the port and starboard cowlings from being interchangeable.

**RECOMMENDATIONS**

2 To permit interchangeability, units ma paint the entire exterior surface of the upper ring cowling matt black.

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF

**REGISTERED**  
ACTM

Prepared By:-  
AMC/SACO/ACR