



LIST OF OVERHAUL MODIFICATIONS
SINGLE ACTING
CONSTANT SPEED CONTROL ASSEMBLIES

(This EO replaces EO 15-30DB-6B dated 31 Oct 61)

TABLE OF CONTENTS

EO NO	DATE OR MOD DATA	DESCRIPTION	OVERHAUL CLASS	LEAFLET ISSUED
15-30DB-6B/1		(Rescinded)		
/2	SB 128	Inspection and Modification	B	No
/3		(Rescinded)		
/4	SB 139	Redesigned Auxiliary Check Valve	B	No
/5	SB 147	Solenoid Valve Rework	B	No
/6	SB 153	Removal of Centrifugal Switch	B	No
/7	SB 157	Locking Solenoid Valve Seat	B	No
/8	SB 169	Auxiliary Check Valve Change	B	No
/9	SB-90	Relief Valve Pressure	B	No
	SB-187	Change, Gov. 4B2-P6 to 4B2-P8		
/10		Modification of Feathering Adaptors Parts 63921-SK29111 and 92063 to the original 63921 Configuration Without Oil Bleed	B	No
/11	SB 102	Modification of the 4G8-G67M Type Governor to the 4G8-G63M Type Governor	A	No
/12		(Rescinded)		

SUPERSEDED
BY C-15-491-000/CD-009
31 Jan 74

TABLE OF CONTENTS (Cont'd)

EO NO	DATE OR MOD DATA	DESCRIPTION	OVERHAUL CLASS	LEAFLET ISSUED
15-30DB-6B/13	10 Jul 61	Governor Cover 69037 with Long Rack Bore		Yes
* /14	27 Jun 62	Addition of Flyweight Cup Oil Drain Holes		Yes

*Asterisks appearing opposite entries denote changes since last issue.

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF