

# DESCRIPTION AND MAINTENANCE INSTRUCTIONS

## ENGINE - COWLING MOUNTING BRACKETS

(This EO replaces EO 05-45B-2Q dated 27 Apr 60)

### INFORMATION

- 1 Cowl mounting brackets 26JU/404-185918 replaces brackets 18S5918, which has had a high rate of replacement, also pads A4-585 which were introduced by modification EO 05-45B-6A/85 and proved highly unsatisfactory.
- 2 Tests have indicated that the new brackets 404-185918 should exceed 3000 hours without difficulty and has had a tendency to decrease the cowling maintenance.

### INSTRUCTION

- 3 The new brackets 404-185918 when required are to be installed as a complete set of nine per engine.
- 4 To prolong the life of the brackets, the support brackets 18S5921 are to be inspected carefully, and any burrs which may exist around the rivet holes are to be removed.
- 5 Re-adjust the cowlings upon installation.

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF

Prepared by:  
AMC/SACO/ACR