Burning (Juli- 1the of)

ROYAL CANADIAN AIR FORCE

EO 05-45B-2U 13 Oct 61

DESCRIPTION AND MAINTENANCE INSTRUCTIONS


CABIN COLD AIR INTAKE PLUGS

INFORMATION

In order to improve the heating system in Expeditor Aircraft, units may manufacture, from unit sources blanking plugs as per Figure 1 and install in the cabin cold air intakes as required.

INSTRUCTION

- 2 Carry out the following instructions:
- (a) Braze slotted head screw 28/AN526-428-32 to washer 28/AN970-6.
- (b) Cut 2 each 2 inches OD rubber washers from 326/402 rubber sheeting 1/2 inch thick.
- (c) Assemble as per Figure 1.






Figure 1

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF