LIST OF APPROVED REPAIR AND SALVAGE SCHEMES WASP R985-AN5 AND AN14B ENGINES

(This EO replaces EO 10A-10AA-3A dated 24 Jan 64)

TABLE OF CONTENTS

| NUMBER | DATA | Piston and TITE Arrangemen | MODELS A | AFFECTED AN14B |
|--------|---|--|----------------------|-------------------|
| | | and Clearances | | |
| 1 | SB1399 | Visual Identification of Shippin | | |
| | | Plugs, Covers and Caps | UAXL (O. T. L. | X |
| 2 | SB1523 | Scintilla Magneto Radio Shield | | |
| | | and Adaptor Rework | UAXL (0.T.1.)E196 | |
| 3 X | SB1534 Rev. A | Removal of Phenolic Resin Coa on Steel Parts | iting | X |
| 4 | SB1546 Rev. A | Master Rod Bearing | X | -SSX |
| 5 | SB1567 Rev. A | Cylinder Attachment Inspection | OTSEZII | |
| | and Supp. 1 Rev. A | and Maintenance | X | X |
| 6 | SB1595 | Rework of Crankshaft Mating Buttfaces at Overhaul | x | X |
| 7 | SB1646 Rev.A | Oil Pump Assembly | X | X |
| 8 | SB1655 Rev. B | Crankshaft Roller Bearings | X | X |
| 9 | SB598 | Exhaust Valve Guides and Boss | es X | X |
| 10 | SB569 | Master Rod Bearing Silver Pla | ting X | X |
| 11 | SB633 Rev.A | Crankcase Through Bolt Washe | rs X | X |
| 12 | SB723 Rev.A | Fuel Pump Driveshaft Clearance | ces X | X |
| 13 | SB1097 Rev. A | Pushrod Cover Packing | X | X |
| 14 | SB871 | Engine Data Plate | X | X |
| 15 | SB1710 Rev.A | Piston Rework | x | X |
| 16 | SB1606 Rev. C Sections A1, A2 and C AMA AMA | Cylinder Attaching Studs and Nu | | Х |
| 17 | SB1669 Rev. A and Supp. 1 Rev. A | Crankcase Cylinder Pad Crack | x | X |

TABLE OF CONTENTS (Cont'd)

| DATA | TITLE MARKET | MODELS A | AFFECTED AN14B |
|-----------------------|---|--|--|
| SB1703 | Cylinder Head Rework | X | Х |
| SB1706 | Starter Drive Shaft Bore Rework | X | Х |
| SB1736 | Helicoil Inserts | Х | х |
| SB1352 Rev. C | Piston and Ring Arrangements and Clearances | ATAG X | NU MA ER X |
| UACL (O.T.I.) E200 | Rework of Valve Clearance Adjusting Screw | X | х |
| UACL (0.T.I.)E196 | Rework of Propeller Oil Control Body Opening | | х |
| SB1739 Rev. A | Governor Accessory Drive Studs | SB1534 Re | x |
| SB1757 | Cylinder Assembly Inspection Of X | | Х |
| OTSE211 | Installation of "O"-ring Seals | | |
| | Propeller Thrust Bearing Cover Studs | | x |
| | SB1706 SB1736 SB1352 Rev. C UACL (O. T. I.) E200 UACL (O. T. I.)E196 SB1739 Rev. A SB1757 | SB1706 Starter Drive Shaft Bore Rework SB1736 Helicoil Inserts SB1352 Rev. C Piston and Ring Arrangements and Clearances UACL (O. T.I.) Rework of Valve Clearance Adjusting Screw UACL Rework of Propeller Oil Control Body Opening SB1739 Rev. A Governor Accessory Drive Studs SB1757 Cylinder Assembly Inspection Of OTSE211 Installation of "O"-ring Seals Propeller Thrust Bearing Cover | DATA TITLE AN5 SB1703 Cylinder Head Rework X SB1706 Starter Drive Shaft Bore Rework X SB1736 Helicoil Inserts X SB1352 Rev. C Piston and Ring Arrangements and Clearances X UACL (O.T.I.) E200 Rework of Valve Clearance Adjusting Screw X UACL (0.T.I.)E196 Rework of Propeller Oil (0.T.I.)E196 Control Body Opening SB1739 Rev. A Governor Accessory Drive Studs SB1757 Cylinder Assembly Inspection Of X OTSE211 Installation of "O"-ring Seals Propeller Thrust Bearing Cover |

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF