

ROYAL CANADIAN AIR FORCE




LIST OF  
OVERHAUL MODIFICATIONS

SCINTILLA MAGNETOS MODELS  
SB9RN, SF9LN-3 AND SF9RN-3

(This EO replaces EO 15-5ADB-6B dated 1 Oct 56)

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF

17 JUN 57



## TABLE OF CONTENTS

EO NUMBER	MOD. DATA	DESCRIPTION	OVERHAUL CLASS.	LEAFLET ISSUED	
15-5ADB-6B/1	SB 194	Safety Wire Air Blast Hood Fastening Screws	B	No	
	/2	SB 244	Plugging of Oil Holes in Magneto Front End Plates and Coil Covers	B	No
	/3	SB 251	Retirement of Overage Coils	B	No
*	/4	(Recinded)			
*	/5	SB 239B	Improved Radio Shielding	B	No
	/6	SB 169	Replacement of Condenser Part 2-755Z with Condenser Part 2-755Y	C	No

\* Asterisks appearing opposite entries denote changes since last issue.

