

ROYAL CANADIAN AIR FORCE



LIST OF  
OVERHAUL MODIFICATIONS

POSITION LIGHT FLASHER  
UNIT 450250-0-3

(PACIFIC BENDIX)

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF

## LIST OF RCAF REVISIONS

<b>DATE</b>	<b>PAGE NO</b>	<b>DATE</b>	<b>PAGE NO</b>
-------------	----------------	-------------	----------------

### NOTE

All new issues, re-issues, rescissions, etc., affecting this list of Overhaul Modifications will appear in the monthly Supplements to the Engineering Order Index EO 00-1-1.

Holders of this Engineering Order are to amend it to reflect changes as they appear in the Supplements in order that an up-to-date list is available for checking purposes.

TABLE OF CONTENTS

EO NUMBER	MOD. DATA	DESCRIPTION	OVERHAUL CLASS.	LEAFLET ISSUED
40-65GB-6B/1	MAB A138/52	Use of Improved Plate and Bearing Assembly		No

