


11 May 60



**LIST OF OVERHAUL MODIFICATIONS
 VARIABLE PITCH AIRCRAFT PROPELLER
 MODELS 22D30, 23D40, 23E50 AND 24D50**

(This EO replaces EO 15-30AB-6B dated 4 Dec 58)

TABLE OF CONTENTS

EO NO	DATE OR MOD DATA	DESCRIPTION	OVERHAUL CLASS	LEAFLET ISSUED
15-30AB-6B/1	ECP #HS 508	Installation of Teflon Corrosion Barrier at Blade Seal Area (Shank Portion)	B	No

SUPERSEDED
 BY 15 Jan 73

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF