

LIST OF SPECIAL INSPECTIONS
SCINTILLA MAGNETOS MODEL SB9RN

(This EO replaces EO 15-5ADB-5 dated 31 Oct 61)

TABLE OF CONTENTS

LATEST DATE	EO NO	TITLE
*	15-5ADB-5/1	(Rescinded) Inspection for Corrosion Between Grounding Tip of Screw Part 2-422Z and its Receptacle in Magneto.

*Asterisks appearing opposite entries denote changes since last issue.

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF