

TITLE WORN BOLT HOLES. AIR DUCT VALVE ASS'Y				REV. NO. 12828		CLASSIFICATION IMMEDIATELY -SU	
PART NO. BEECH 407-188862-1		PART NAME VALVE ASSEMBLY OIL RADIATOR AIR DUCT.		DRAWING NO.		COPY NO.	
USE OF Dwg.		REVISION OF STOCK		APPROVED BY		DATE	
ALTERED				BREWSTER			
CONDENSED		CHECK BLOCKS AFFECTED	NOT APPROVED	USE TO DUALSTAMP	HOWARD	COULD	AS ORDERED
STOP ORDER/RELEASE							
NEW DRAWING		PARTS COMPLETED					
REVISED DRAWING		PARTS IN PROCESS					
VARIATION		TOOLING					
OBsolete NOTICE		RAW MAT'L					
USE AS NOTED	✓	INTERCHANGEABILITY AFFECTED		STRENGTH AFFECTED			
		YES	NO	YES	NO		
APPROVAL		ENGINEERING		CONTRACTS-GENERAL		CUSTOMER	

THE AN3-11A BOLT SECURING THE 188863 ARM ASSEMBLY TO THE 188864 SHAFT ON THE VALVE ASSEMBLY MAY BE REPLACED BY AN386-1 OR -2 TAPER PIN WHEN THE HOLES FOR THE BOLT ARE WORN.

(REF: T&F 0270S)

May 1/59